## BLAST-IT-ALL<sup>(R)</sup>

LARRY HESS & ASSOCIATES, INC. SALISBURY, NC 28147

TOLL FREE: (800) 535-2612 PAX: (704) 638-9311

# STRIP 'N' VAC

## PLASTIC MEDIA PAINT STRIPPER

- HI STATIC VACUUM RECOVERY
- 120 VOLT ELECTRICAL SERVICE
- 25 FT, VACUUM RECOVERY HOSE
- NON CLOG PICK UP WAND
- PULSE JET CARTRIDGE CLEANING
- MAGNEHELIC GAUGE / FILTER MONITOR
- QUICK RECOVERY
- DEBRIS SCREEN
- 10 CU, FT, STORAGE HOPPER
- DEADMAN CONTROLS
- ADJUSTABLE MEDIA FLOW VALVE
- 25 FT. BLAST HOSE WITH 5 / 16 CARBIDE NOZZLE
- 90 CFM @ 60 PSI REQUIRED 25 HP (5 / 16 NOZZLE)



BLAST



#### STRIP-N-VAC™

LARRY HESS AND ASSOCIATES, INC.
BLAST-IT-ALL®
P.O. BOX 1615
SALISBURY, NC 28145

WWW.BLAST-IT-ALL.COM

MANUAL NUMBER: 507

#### TABLE OF CONTENTS

| PAGE | FIGURE |                            |
|------|--------|----------------------------|
| 1    | _      | SET-UP INSTRUCTIONS        |
| 1    | _      | OPERATING INSTRUCTIONS     |
| 2    | 1      | RECLAIM & HOPPER           |
| 3    | 2      | PICK-UP TUBE               |
| 4    | 3      | 1 CU FT PRESSURE SYSTEM    |
| 5    | 4      | 3 CU FT PRESSURE SYSTEM    |
| 6    | 5      | DUST COLLECTOR             |
| 7    | 6      | SCREEN DRAWER              |
| 8    | 7      | PULSE HEADER               |
| 9    | 8      | FILTER CARTRIDGE           |
| 10   | 9      | DUST COLLECTOR STAND       |
| 11   | 10     | ELECTRICAL DIAGRAM         |
| 12   | _      | MACHINE WARRANTY           |
| 13   | _      | WARRANTY REGISTRATION FORM |

#### WARNING

DO NOT USE SAND. SAND WILL CAUSE SILICA DUST, WHICH IS THE CAUSE OF SILICOSIS DISEASE, A CONDITION OF MASSIVE FIBROSIS OF THE LUNGS. THIS STATEMENT INDICATES POTENTIAL PERSONNEL HAZARD.

FAILURE TO COMPLY WITH THESE INSTRUCTIONS

MAY RESULT IN PERSONAL INJURY.

**WEBSITE CONCERNING SILICOSIS:** 

http://www.osha.gov/Silica/IT69D 1.html

#### STRIP-N-VAC™

#### SET-UP INSTRUCTIONS

#### \*\*\* READ BEFORE OPERATING EQUIPMENT \*\*\*

- 1. Remove equipment from pallets.
- 2. Connect compressed air to air filter or pipe string.
- 3. Lift and attach reclaim to debris screen flange.
- 4. Connect smaller flex hose to side inlet on reclaim and pick-up tube.
- 5. Connect 5" flex hose from top of reclaim to inlet on dust collector.
- 6. Connect compressed air line to air header / regulator on dust collector pulse control.
- 7. Plug dust collector supply cord into dedicated 120 V receptacle.

#### **OPERATING INSTRUCTIONS**

#### \*\*\* READ BEFORE OPERATING EQUIPMENT \*\*\*


#### 1. To Load Media:

- A. Turn Dust Collector on.
- B. Place media pick-up tube in drum of media.
- C. Fill system until media is at site gauge on hopper.


#### 2. To Blast:

- A. Turn on compressed air.
- B. Have operator suit-up with protective clothing.
- C. Grasp nozzle and point away from operator.
- D. Depress (Safety Deadman).
- E. Adjust air regulator 40 60 PSI.
- F. Adjust media valve as needed for proper media flow.


### \* THERE SHOULD BE A SMALL AMOUNT OF MEDIA AND A LARGER AMOUNT OF COMPRESSED AIR COMING FROM NOZZLE.




PAGE 2 FIGURE 1




PAGE 3 FIGURE 2




PAGE 4 FIGURE 3




PAGE 5 FIGURE 4




PAGE 6 FIGURE 5




PAGE 7 FIGURE 6




PAGE 8 FIGURE 7



PAGE 9 FIGURE 8





PAGE 11 FIGURE 10

#### WARRANTY

Larry Hess & Associates, Inc. Warrants to the original purchaser the merchandise sold to be free from defects in material and workmanship under normal use and service for a period of one (1) year. Upon prompt notification by the buyer, to LHA, components that are determined by LHA to be defective will be repaired or replaced at no additional charge, F.O.B. our factory.

Manufacturer shall have the right to inspect prior to replacing all merchandise in question.

This warranty does not apply to parts that are directly involved in the blasting operation. Example: gun, gun parts, viewing window, hose, gloves, etc.

Manufacturer shall not be required to pay any removal or installation charges whatsoever under this warranty.

Manufacturer shall not be liable for prospective profits, special or consequential damages, nor shall any recovery of any kind against manufacturer be greater in amount than the cost of repairs of defects in workmanship.

This warranty does not apply to damage caused by accidents, damage in transit, alterations by unauthorized personnel, abuse or damage by flood, fire, or acts of God, nor by artificially generated electric currents or any other cause whatsoever except defects in material or factory workmanship.

In all cases, defective parts must be returned to Larry Hess & Associates, Inc. before credit is issued.

If genuine BLAST-IT-ALL® replacement parts are not used, the warranty is void.

This warranty is in lieu of all other warranties expressed or implied and releases Larry Hess & Associates, Inc. of all other obligations and liabilities whatsoever. This warranty neither assumes nor authorizes any person to assume any obligation other than those specified by this warranty.

#### **WARNING**

DO NOT USE **SAND**. SAND WILL CAUSE SILICA DUST, WHICH IS THE CAUSE OF SILICOSIS DISEASE, A CONDITION OF MASSIVE FIBROSIS OF THE LUNGS. **THIS STATEMENT INDICATES POTENTIAL PERSONNEL HAZARD. FAILURE TO COMPLY WITH THESE INSTRUCTIONS MAY RESULT IN PERSONAL INJURY.** 

BLAST-IT-ALL® Larry Hess & Associates, Inc. Airport Industrial Park 185 Piper Lane P.O. Box 1615 Salisbury, NC 28145-1615